L3057 LAND CORNER PRESERVATION RECORD It is the purpose of this record to preserve the location of a survey or land corner monument that may be disturbed, removed or inaccessible due to road construction or other activity. City, Village, Town: Section: Town: Range: County: 6 E. Oneida **Nokomis** 36 Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 Approximate location within corner or other subdivisional corner; a monument called for in a deed; a monument shown on a Section 11, T36N, R6E survey map or plat etc and in what GL or ¼ - ¼ section or subdivision the monument is located. May 21, 2015: I found and marked the erroneous 1-3/4" diam. iron pipe depicted on survey maps C-2296 and B-7506. Road construction will not affect the corner point. 3606111020 Plan view map of landmark monument location with bearing and distance ties to a minimum of four described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material or indicate datum & coordinates if tied out using GPS. Indicate what was reset. **NORTH** MAP # 63057 DATE FILED 2-2 3-16 DESCRIPTION FILED ONEIDA CO. SURVEYOR'S OFFICE Seal: PROFESSIONAL LAND SURVEYOR CERTIFICATE: This land corner was referenced out in advance of road construction or other



This land corner was referenced out in advance of road construction or other activity as an act of preserving survey evidence or monuments. This corner has not been tested for its accuracy during the course of this preservation. It is recommended that those using the corner position evaluate and verify it prior to use in a survey or other use.

I hereby certify that I am a duly licensed Professional Land Surveyor in the State of Wisconsin; that the location of this Survey or Land Corner was referenced by the, or under my direct supervision and control and that the information shown on this record is true and correct to the best of my knowledge and belief

Signature

JAN-22, 2016

ate