


13 39 R. 9 E. W.

① Meander loc - East line - South of Aldridge



② Meander loc - East line - North of Aldridge

③ E 1/4 NE 1/4

RECEIVED & FILED #	16160
Oncida County Surveyor's Office	
Date	11/5/88
By	J. D. W. R.
OCS Area #	

④ NE Cor. Sec 13 at 74.726 north of SE Corner (Bardow)  
at 5.86 (orig. 5.60) north of creek, on I.P. Is also 30.656 east  
of E.M.C. Katherin Lake. (Jlg 1972)

⑤ N<sup>1/4</sup>NE<sup>1/4</sup> at 20.522 set 2" pipe for "8 Cor. south of creek 60± lbs.  
B.T. MR 9" - N33°E - 0.499 ch.; PW 14" - S88°E - 0.933 ch. Bardows pipe is  
N45°E - 0.052 ch. (Jlg 1972)

⑥ Member Cor. - North Line - East side Katherin at 30.656 west of NE Cor.  
(~~Step 1~~) replaced Bardows pipe with w.c.d. pipe. Corner is 37± lbs east  
of lake & N45°W - 90 lbs from north side of creek. B.T. PW 10" - N49°E - 0.135 ch.  
Tom 6" - N29°W - 0.437 ch. (Jlg 1972)

1) N<sup>1</sup>/<sub>4</sub> Sec 13 at 41.044 each way. (~~July 1972~~) set D.M.R. pipe flush  
with ground 1.13± ch. north of Katherin Lake. BT PW 12" - S79°E - 1.324 ch.;  
W 12" - S71°E - 0.720 ch.; PW 18" - S50°W - 1.111 ch. Borders pipe  
S 09°E - 0.862 ch. (July 1972)

2) Meander Cor - West Line - South of Katherin Lake at 34.967 north of SW  
Cor of 3.928 south of <sup>1</sup>/<sub>4</sub> Cor in lake replaced Maine's scribed wood post with  
V.C.D. pipe. New B.T. PN 12" - S09°E - 0.390 ch.; PW 12" - S81°W -  
0.851 1/2 ch.; S. cor. small boat house - S64°E - 0.120 ch. (July 1972)

3) W<sup>1</sup>/<sub>4</sub> SW<sup>1</sup>/<sub>4</sub> at 19.447 set 1" I.P. painted red for <sup>1</sup>/<sub>8</sub> Cor. 50± ch. west  
of creek BT. BW 11" - S71°W - 0.511 ch.; MH 9" - N51°W - 0.418 ch.  
Northwoods pipe bears S1°W - 0.268 ch. (July 1972)