


L628

S 24 - 39 - 9 W.

① E 1/4 SE 1/4



② E 1/4 Sec 24

③ E 1/4 NE 1/4

RECEIVED & FILED 16 284
Onida County Surveyor's Office
Date 1/5/88
By M.A.
OCS Area #

④ NE Cor. Sec. 24 (Replaced scrub wood post which were - or
B.T. present. Tree 8" (dead) $N6^{\circ}E$ - 0.054 ch.; Cedar 10" - $S85^{\circ}E$ - 0.306 ch.)
Cedar 9" - $S2^{\circ}W$ - 0.304 ch.; Cedar 9" - $N83^{\circ}W$ - 0.319 ch. (Avg 1892-)

⑤ $N\frac{1}{4}NE\frac{1}{4}$

⑥ $N\frac{1}{4}Sec 24$

⑦ Meander Cor. - North Line - East of Cranberry

⑧ Thordarson Cor - North Line - West of Contry

24-39-9 L628

24 Dec. 24 Replaced Main's wood post & Griffins I.P. with
wcd pipe. New Bt. MH8" - N36°E - 0.860 ch.; BW6" - S62°W - 0.248 ch.
BW9" - N36°W - 0.282 ch. (Jlg 1972)

⑩ w¹/4 NW¹/4

D W 1/4 Sec 24 at 81.80 east of W 1/4 Cor. Sec 23
fell 1.13 south of 1/4 post. Nothing for bearings, post OK. Set post
PW 10" (dead) - S 60° E - 26 ft. (this pt. must be for W 1/4 Sec 23) Vayda
6/11/1966