



① N¹/₄ NE¹/₄ at 19.917. B.T. point is
 BW 12" - S 76° W - 0.623 ch. New B.T. BW 7"
 N 1° W - 0.612 ch. Borders 48' is 3⁺ feet south
 of ours. (Jlg 1964)

RECEIVED & FILED L670.
 Onrda County Surveyor's Office
 JAN. 18 1968
 Date.....
 By.....
 OCS Area #.....

② N¹/₄ Sec 25 at 39.834 west of NE Cor & 39.782 west east of NW Cor.
 W.C.D. ~~point~~ B.T. point PW 22" (exp.) - N 67° E - 0.866 ch.; PN 24" (exp.)
 N 74° W - 0.541 ch.; Vincent's B.T. BW 9" - N 29° E - 0.479 ch. New B.T. BW 7"
 N 47° W - 0.603 ch (Jlg 1964)

③ N¹/₄ NW¹/₄ at 19.891 set 1" I.P. Vincent's B.T. is now BW 7" - S 86° W
 0.276 ch.; New B.T. BW 7" - N 53° W - 0.568 ch. Vincent's well point is
 6⁺ feet Northwestly. (Jlg 1964)

DNW Cor. Sec 25 WCD pipe in 18" of water. any corner on 11" pipe etc.
Hassler BT are PW 36" - N71°E - 1.364 ch.; SB 4" - S14°E -
2.652 (now rolled off.) Bernell's BT are PN 16" - N66°E - 1.500 ch.;
OW 12" - S 83°E - 1.185 ch. (Dg 1964)

SW 1/4 NW 1/4 at 20.038 1/2 set 1" I.P. PJ 10" - S89°W - 0.066 ch.;
PJ 8" - S 28°W - ~~0.122~~ 0.325 ch. (Dg 1964)

SW 1/4 Sec 25 WCD pipe in sand pit, 22± feet south of E of dirt
road. PN 18" - S82°W - 1.562 ch.; BW 4" - N52°E - 1.754 ch. (Dg 1964)
WCD pipe found Bent over from snow plow, reset ^{flush with} from ^{both} BT's present (Seymour 8-24-77)

SW 1/4 SW 1/4 at 20.038 1/2 set 1" I.P. in marsh just west of N/S
peat road. New BT, both knife blazed. SB 1" - S28°W - 0.871 ch.; PW 1 1/2"
S76°E - 1.687 ch. (Dg 1964)