


L688

S 38 R 8

①
0



Iron Jpg. PJ 10" - 55°W -
PJ 10" - N84°W - 0.257 ch. (?)

RECEIVED L688

Oneida County Governor's Office
Date
By
OCS Area #

② N 1/4 Sec 7 Found overburden of
soil set 1/4 Cor at 38.26 east of N
55°W - 11 (Vaughn 4/11/07) to
PN 16" - N56°W - 0.610 ch. at

between NW Cor & west bank of River
PN 8" - S5°W - 42 ; open 5" -
PW 18" - N33°E - 0.260 ch. j
+ off NW Cor ()

③ N 1/4 NW 1/4 Set 1/8 foot. P-
ch. (Vaughn 4/11/07) at 16.76 east;
MR 4" - N19°E - 0.375 ch; Doh 4"

"E - 0.085 d; PW 3" - S10°W - 0.295
20.72 west of R 1/4. Wood post
0.470 ch. C ()

L688

1688

④ NW Cor. Sec 7 No sign of org cor. lot post at 111.91 north of org. M.C. on north side of Miss River. PW (off) 18" - N 62° E - 0.345 ch.; PW (off) 20. S 21° W - 0.645 ch. (Vaughn 4/11/07) Found Vaughns off. N 59° E - 34. PW 8" S 39° E 0.210 ch.; PW 10" - N 89° E - 0.250 ch. Boss cap. (?)

⑤ W 1/4 NW 1/4 lot 1/8 sec. PN (stab.) 7" - N 12° W - 0.205 ch.; PN (stab) 10" - S 35° E - 11 (Vaughn 4/11/07)

⑥ W 1/4 Sec 7 No sign of org cor. lot post at 71.69 1/2 north of org. M.C. on north side Miss. River. PN (stab) 8" - S 42° E - 74; PN 8" - N 43° W - 0.415 ch. (Vaughn 4/11/07)

⑦ W 1/4 SW 1/4 lot 1/8 post. PN (off) 8" - S 11° E - 35; PN (off) 8" - S 9° W - 70 (Vaughn 4/11/07)

See 7-38-8
I 688

⑧ See Cor. See ^{I 688} No sign of org. cor. Set. post at 31.63 north of orig. M.C. on north bank of Wis. River. PN 16" - N 24° W - 0.105 ch. DN 20" - N 84° E - 2.06 ch (Vaughn 4/11/02) Vaughn(?) stp. N 27° W - 1.015 ch; MH 6" S 49° W - 0.190 ch; Oak 7" - N 33° W - 0.518 ch. (?)

⑨ S $\frac{1}{4}$ SW $\frac{1}{4}$

⑩ Meander Cor. - South Lns - West of River

⑪ Meander Cor. - South Lns - East of River

I 688

I 688

⑫ S $\frac{1}{4}$ Sec 17


⑬ S $\frac{1}{4}$ SE $\frac{1}{4}$

⑭ Meander Cor. - North line - East of River at 56.49 east of NW cor. fell 2.51
north of orig M.C. on east bank of River & report (Vaughn 4/11/07)

⑮ Meander Cor - E/W $\frac{1}{4}$ line - West of River at 38.20 east of W $\frac{1}{4}$ cor set
M.C. 95 links west of river. PW 14" - N41°E - 0.255 ch.; PW 18" - S21°W -
0.420 ch. (Vaughn 4/11/07)

L688

S. 2 + 38 + R. 8



① N 1/4 NE 1/4 Iron Jpg. PJ 10" - S 55° W -
0.388 ch.; PJ 10" - N 84° W - 0.757 ch. (?))

② N 1/4 Sec 7 Ground overrun of 3.00 ch between NW Cor & west bank of River
so set 1/4 Cor at 38.26 east of NW Cor. sec 7. PN 8" - S 55° W - 42; open 5" -
S 59° W - 11 (Vaughn 4/11/07) Brass cap. PW 18" - N 55° E - 0.260 ch.;
PN 16" - N 56° W - 0.610 ch. at 37.48 east of NW Cor. (?))

③ N 1/4 NW 1/4 Set 1/8 post. PJ 8" - N 27° E - 0.085 ch.; PW 8" - S 10° W - 0.295
ch. (Vaughn 4/11/07) at 16.76 east of NW Cor & 20.72 west of N 1/4. Wood post
MR 4" - N 19° E - 0.375 ch; Ash 4" - N 73° W - 0.470 ch. (?))

④ NW Cor. sec 7 No sign of ogl cor. Set post at 111.91 north of ogl L. b 88
MC on north side of Wks River. PW (stb) 18" - N 62° E - 0.345 ch.; PW (stb) 20"
S 21° W - 0.645 ch. (Vaughn 4/11/07) Found Vaughns stb. N 59° E - 34. PW 8"
S 39° E 0.210 ch.; PW 10" - N 82° E - 0.250 ch. Gross cap. (?))

⑤ W 1/4 NW 1/4 fel 1/8 post. PN (stb.) 7" - N 12° W - 0.205 ch.; PN (stb.) 10" - S 35° E - 11
(Vaughn 4/11/07)

⑥ W 1/4 sec 7 No sign of ogl cor. Set post at 71.69 1/2 north of ogl MC on north
side Wks. River. PN (stb.) 8" - S 42° E - 74; PN 8" - N 43° W - 0.415 ch. (Vaughn
4/11/07) found 1" i.p. from Northwoods Surveyor's 1970 made more BT^s, 1987 Seymour

⑦ W 1/4 SW 1/4 fel 1/8 post. PN (stb.) 8" - S 11° E - 35; PN (stb.) 8" - S 9° W - 70
(Vaughn 4/11/07)