


SEC. 27 T. 39 N. R. 7 W. E



① W.C.D. Brass Cap 12-15' in Marsh  
 BT<sup>s</sup> (old) pine stump S70°E 77.25'  
 P.R. 20" S54°E (No dist)  
 (New) B.W 9" N60°E 31.45' (Not scribed)  
 P.W 5" North 33.50' (" " )  
 See Corner file

(Visser's, 1979)

② W<sup>1</sup>/<sub>4</sub> W.C.D. Brass Cap w/wood post  
 BT<sup>s</sup> (old) P.W. 26" S01°W 18.0' w/location marker  
 OAK 10" S72°W 22.35'  
 (New) OAK 10" N12°W 9.30'  
 OAK 6" N87°E 20.25'  
 See Corner file


(Visser's, 1979)

③ E<sup>1</sup>/<sub>4</sub> - SE<sup>1</sup>/<sub>4</sub> (sat) 1" Iron pipe (1979)  
 BT<sup>s</sup> P.W. 8" S12°W 20.80'  
 F.B. 8" S84°W 22.20'  
 (OH) P.W. 20" N41°W 75.50'  
 (Note) A 1" I.P. Falls N 22°04' E 36.57'

RECEIVED & FILED # 17864  
 Oneida County Surveyor's Office  
 Date: APR 22 1999  
 By: .....  
 OCS Area #: .....

(Visser's 1979)

④ ~~W<sup>1</sup>/<sub>4</sub>~~ NW<sup>1</sup>/<sub>4</sub>



⑤ N<sup>1</sup>/<sub>4</sub> NE<sup>1</sup>/<sub>4</sub> set 1" i.p. BT<sup>s</sup> Asp 2" S65°E 17.08', Asp 2" S18°W 19.13' Seymour 7/25/84

⑥ N<sup>1</sup>/<sub>4</sub> 27 See Corner file

⑦ N<sup>1</sup>/<sub>4</sub> NW<sup>1</sup>/<sub>4</sub> set 1" i.p. (in valley) BT<sup>s</sup> MR 10" S36°E 12.02', BW 10" S78°E 44.10'  
Seymour 7/25/84

⑧ SE<sup>1</sup>/<sub>16</sub>  
2" I.F. set, Pine stp. S25E 5.5' (Griffin 1966)