


18 38

79




① SW CORNER. GLO Brass cap (1923) B.T.'s.
 Bw 8" N20E 76; Bw 6" S52 1/2 E 1.77;
 A 4" S47 3/4 W 1.69; Bw 5" N68 1/2 W 1.11.

RECEIVED & FILED **4809**
 On the County Surveyor's Office
 Date **APR 22 1988**
 By **S. H.**
 DCS Area #.....

1804

18. T. 38 N. R. 7 W.



① SW Corner. GLO Brass cap (1928) B.T.'s -
 Bw 8" N20E 76; Bw 6" S52 1/2 E 1.77;
 A 4" S47 3/4 W 1.69; Bw 5" N68 1/2 W 1.11.

could not find, BT's all gone, mon-gone
 from Hwy construction

② SQUARED ^{AND SCRIBED} WOOD POST IN ROCK PILE; 6" DIA. SCRIBED
 OAK B.T. 20'± WEST; 6" DIA. SCRIBED OAK B.T. 35'
 NE. (FROM RECORD FILE NOTES) $\sqrt{2}$
 WLD brass cap found, BT Oak 16" N21°E 39.65', NW BT is a stp
 Mids BT's MH 8" N54°W 15.93; OR 8" N57°E 22.73; Bw 14" east 28.86'
 (Seymour, French, 11/17/86)

~~① SW~~

① SW 18 See 38-7 book

③ thru ⑧ and ② see 38-7 book