
Glen Barker Herb Wagoner SURVEYO SCONS Managada ...HANSEN PHILIP T ARGONNE, S-498 WIS.



O = Corner monument restored.

brept In Boomer

.Deputy

CERTIFIED LAND CORNER RESTORATION

Index No. L-24

History of original corner establishment:

1/4 line from recovered and established 1/4 corners to establish the C 1/4 corner. Set EC 1/16 corner at 19.67 chains intermediate. Set wood post and marked NBTs - White Birch 7" S60°W, 20 links; White Birch 4" S20°E, 13½ links. Corner established by H.C. Lawrence, Registered Land Surveyor, in 1958. Ran E-W & N-S

....., do hereby

SS

Description of corner evidence found:

Recovered 4" cedar post, squared and scribed EC 1/16 S13, EC 1/16 S13 in fair condition. Recovered White Birch 7" (10") S60°W, 20 links, scribed EC 1/16 BT.

White Birch 4" (6") S20°E, 13.5 links, scribing grown over.

Replaced cedar post with 12" iron pipe with 2" brass cap, stamped: Description of monument and accessories I established to perpetuate the original location of this corner.

Built rock cairn around base of monument.

Marked NBT - Maple 6" S21"W, 6.1 links, scribed 1/16 BT.

T35N R11E EC 1/16 S 13 CPI-1977 S498

Daria Verage Kuch	instrument was filed in this office for record on the at 122 o'clock A.	Office of Register of Deeds, County of	Signature Thillie Standar.	Dated at Rhinelander
Kuelm	r record on the		(County Surveyor, Registered Land Surveyor, (County Surveyor, Registered Land Surveyor, or other duly authorized official)	, Wis., this 9th day of
	day of Jerna 1921	Oneida , I hereby certify that the within	Surveyor Registration No. 8-498	of June 19.77

3511132010