

Note Description is provided on a separate sheet

Section Corner

Bearings are based on the North Section line of Section 5 which bears S86°15'00"E as being used in a previous survey.


- ⊙ VILAS CO ALUMINUM CAPPED MONUMENT
- IRON PIPE - BRASS CAP MONUMENT
- 1" DIA IRON PIPE FOUND IN PLACE
- 1" X 24" IRON PIPE SET THIS SURVEY
- △ COMPUTED POSITION
- ( ) RECORD BEARING AND DISTANCE

NOTE DESCRIBED ORIGINAL CORNER FALLS IN CREEK

Part of the  
 SW1/4 of the NE 1/4  
 Section 5, T39N, R11E  
 Town of Three Lakes, Oneida County, WI

**Surveyor's Certificate**  
 I hereby certify that I have surveyed and mapped the lands shown hereon and that, to the best of my knowledge and belief, said survey and map is a true and correct representation thereof, and that I have complied with the Wisconsin Administrative Code A-E 7.  
 Dated this 27th day of October, 2003

*Kip W. Soder*  
 Kip W Soder R.L.S #1731  
 Soder Surveying  
 Three Lakes, WI. 54562



Survey For:  
**Marjorie Davis Living Trust**  
 c/o Ward Davis  
 25460 Bradbury Lane  
 Hockley, Texas 77447

Scale 1" = 80' Date 10-27-2003 Drwn. By' D.J.B

**Soder Surveying**  
 Three Lakes, WI. 54562

Drw No.  
 804

MAP # A 1297  
 DATE FILED DEC 05 2003  
 BY PCD  
 DESCRIPTION FILED  
 ONEIDA CO. SURVEYOR'S OFFICE