

RECEIVED & FILED # A203
 Oneida County Surveyor's Office
 Date FEB. 10 1986
 By MJH
 OCS Area #.....

Erroneous 1/16 Corner

South border of pine plantation

Old fence line

30' W. Pine N70°W 80.9'
 4' N. Pine N40°E 6.0'
 1/16 Corner

N88°05'E
 399.1'

East border pine plantation

Bearings Solar

- = iron pipe found in place
- = iron pipe set
- ⊕ = axle shaft set
- △ = soil boring location

North Parcel
 9.0 Acres

Part of
**GOV'T. LOT 6,
 SECTION 25,
 T38, R7E**
 Oneida County, Wis.

PARCEL 1 & REMAINDER contain no slopes equal to or greater than 15% and the contour information shown thereon is accurate and true to the best of my knowledge and belief.

ADDED PARCELS 1 & REMAINDER JUNE 1974
NORTHWOODS SURVEYORS INC.

Robert H. Kinat
 Land Surveyor

Scale 1" = 100' February, 1872


400.0'
 N85°-23'E
WOLFE ROAD
 N85°-23'E 412.5'
 400.0'

South Parcel
 2.6 Acres

- Remainder -
 1.58 Acres

HERBERT MOORE
 Oneida County Surveyor
 Oneida County, Wisconsin
 Oneida, Wisconsin 54501

14' W. Pine S39°E 82.9'
 Nail in power pole
 Y24°W 94.5'



1/8 Corner
 8' W. Pine N84°-W 46.3'
 8' N. Pine S35°E 54.8'

399.1'
 N88°38'E 2422.3' to Meander Corner

JUN 4 1974