

Crystal Lake Thoroughfare

NOTE: THIS PIPE DOES NOT CHECK WITH PLAT. MAY HAVE BEEN SET WRONG OR MOVED.

THE PURPOSE OF THIS SURVEY WAS TO FIND AND MARK THE EXTERIOR CORNERS ONLY. BEARINGS AND DISTANCES ARE ALL FROM THE PLAT.

- 4 -

- 3 -

Lake Forest Plat

Located in

Gov't. Lot 5 & NW1/4-NE1/4
Section 16, T 38 N, R 11 E
Township of Three Lakes, Oneida County, Wisconsin

Crystal Creek Lane

75'
Radius

NW-NE

Gov't. Lot 2

Gov't. Lot 5
Gov't. Lot 6

(N 89°04'09"W 488.00')

Not Meandered

Not Meandered

(N 73°28'39"E 132.27')

(S 77°56'31"E 104.82')

(N 71°20'23"E 150.00')
148'±

(S 39°35'07"E 240.29')
253'±


(N 25°23'43"W 257.22')

Not Meandered

(S 30°26'34"E 129.31')
(A = 155.90')

(S 00°00'00"E)
(11.05')

SCALE: 1" = 50'



-SURVEY CERTIFICATE AND WAIVER-

Pursuant to Chapter A-E 7 of the Wisconsin Administrative Code, Eagle Landmark Surveying, Inc. is required to meet certain Minimum Standards for Property Surveys as specified in Sections 7.01 through 7.07 of this code. Our client has agreed to exclude certain surveying work from these requirements as allowed in Chapter A-E 7.01 (2).

The requirements of Chapter A-E 7 of the Wisconsin Administrative Code's Minimum Standards for Property Surveys which have been waived are listed below:


- Field measurements and angles as described in (A-E 7.06).
- Legal description prepared for this property (A-E 7.04).
- Monuments marking all property corners (A-E 7.03 & 7.07).
- Tie to a Public Land Survey System Corner (A-E 7.04).

I hereby certify, that to the best of my knowledge and belief, I have complied with the remaining requirements of Chapter A-E 7 of the Wisconsin Administrative Code, Minimum Standards for Property Surveys. DATED THIS 26TH DAY OF MARCH, 2009.

JAMES L. WILL, RLS #1410

-Legend-

- 1" IRON PIPE FOUND IN PLACE
- ⊖ 2" IRON PIPE FOUND IN PLACE
- 2" IRON PIPE AS SHOWN ON PLAT
- () BEARING AND DISTANCE OF RECORD



Survey For
Richard Pyle
365 East Cedarvale Road
Tucson, AZ 85704

SCALE 1"=50' DATE 03/25/2009 DWN. BY. J.L.W.

Drawing No. **E3419**
Eagle Landmark Surveying, Inc.
5035 Hwy. 70 West, Eagle River, WI 54521
P & F (715)479-9610 eaglelandmark@verizon.net

MAP # A 2273

DATE FILED 6/24/09

BY J.H.

DESCRIPTION FILED

ONEIDA CO. SURVEYOR'S OFFICE