RECEIVED & FILED #..... Oncida County Surveyor's Office Inman . Foltz and Associates, Inc. Date JUL 1 7 1992 Gov't. Lot ___8 architects engineers surveyors 8612 highway 51 north (715) 356-9485 Section __3 OCS Area #..... Township 38 North Range <u>11</u> East County Oneida State of Wisconsin ■ = wood lath set at approx. corner ⊙= /" iron pipe found = 1-3/4" iron pipe found - Town S Road -Road = 1-1/2" iron pipe found N83°07'30"E 140.00 Bearings NOTE: All dimensions shown are from the Plat Utility Ease. County Plat of Stanzel Farm. -18uuu Y Y uuu 1.84 acres nun Y Grun LP Tank Meander Corner Scale: Big 1"=100' Stone Lake 100,050,000,000,000° This survey was made for Darrell Schmitz , hereafter referred to as Client. A written agreement has been made between Inman Foltz and Associates, Inc. and Client to exclude this survey from the requirements of Wisconsin Administrative Code Chapter A-E 7. The requirements not being necessary for location of the parcel(s) owned by Client has not been made; 21 Monuments were not set to mark the corners of the parcel(s); 3) No legal description of the parcel(s) has been provided or shown on this map; 4) The exact lengths and bearings of the boundaries of the parcel(s) owned by Client have not been shown on this map; 5) The relationship to the surveyed owned by Client have not been shown by bearing and distance on this map; and 6) The measurements made in performing this survey work do not linear measurements, or 30 seconds per angle but not more 120 seconds

This survey is correct to the best of my knowledge and belief.