
A630 RECEIVED & FILED #..... Inman • Foltz and Associates, Inc. Oneida County Surveyor's Office architects surveyors Date. JUL. 1 7 1992 8612 highway 51 north [715] 356-9485 ninocqua, wisconsin 54548 Section __10 OCS Area #..... Township 38 North Range <u>6</u> East County Oneida State of Wisconsin Bearings Magnetic V.3 CSM p.823 1⁷³ V.4 GSM p.937 (N89°13'41"E, 1312.25') 1312.37 N89°13'41"E N89°18'41"E G.L. 3 S1/16 Corner (131.58') 157.81' 2" iron pipe 1-1/2" iron pipe found SE 1/16 Corner 2" iron pipe found 8" W.Birch, N43°W, 5.8' const. debris over line 1/16 Line by J. H. Fisher in 1980. (See V. CSM p.823) SW-SE SE-SE

() = Previously recorded

This survey was made for Gale Fisher , hereafter referred to as Client. A written agreement has been made between Inman-Foltz and Associates, Inc. and Client to exclude this survey from the requirements of Wisconsin Administrative Code Chapter A-E 7. The requirements not being complied with are: 1) A field survey traversing and connecting monuments necessary for location of the parcel(s) owned by Client has not been made; 2] Monuments were not set to mark the corners of the parcel(s); 3) No legal description of the parcel(s) has been provided or shown on this map; 4) The exact lengths and bearings of the boundaries of the parcel(s) owned by Client have not been shown on this map; 5) The relationship to the surveyed parcel(s) of the monuments used for determining the location of the parcel(s) owned by Client have not been shown by bearing and distance on this map; and 6) The measurements made in performing this survey work do not conform to the minimum accuracy requirements of 1 part in 3000 for linear measurements, or 30 seconds per angle but not more 120 seconds total angular closure for closed traverses.

This survey is correct to the best of my knowledge and belief.



Scale: 1" = 200'