
Recorded in Volume 2 of Survey Maps on page 363.

724 DATE FILED .. FEB 0 6 1995 DESCRIPTION FILED ONEIDA CO. SURVEYOR'S OFFICE



## SURVEYOR'S CERTIFICATE

I, J. David Manson, Registered Land Surveyor No. S-1339 hereby certify that we have surveyed the above described property; that this plat is an accurate survey and a true representation thereof and correctly shows the exterior boundary lines and the correct measurements thereof; that we have made such survey by order of Howard Martin, and that we have complied with Chapter 236.34 of the Wisconsin Statutes.

December 20, 1994

Recovered, verified, and marked iron monuments at the corners of Lot 1 as follows:

- 3/4" iron rod found in place and marked with flagged lath
- //// = Lot lines marked approximately with fluorescent surveyor's flagging ribbon.

This survey was completed for the purpose of locating existing lot corners and flagging approximate lot lines by the order of Phillip Kimball, who has executed a written waiver for all other requirements of Wis. Adm. Code Chap. A-E 7. A closed traverse was not made and the minimum accuracy is 1 part in 100 and plus or minus 2°.

