MAP #	A 0 875
DATE FILE	APR 1 9 1999
ву	<i>B</i>
DESCRIPTION FILED	
ONEIDA CO	. SURVEYOR'S OFFICE

NOTE: This survey was

done to mark the North 8 South lines of Parcel B as Section Corner, established by Bill Bandow in Survey #9134. Bearings are based on said Bandow Map. Being a Part of Lot 1 of C.S.M. 1128 Lot 2 of C.S.M. #1128
Located in the Lot 2 of C.S.M. 1128 NE 1/4-NE 1/4 Sec. 10, T 37 N, R 9 E Township of Pine Lake Oneida County, Wisconsin -SURVEY CERTIFICATE AND WAIVER-N 86°44'59"E 1196.29" Lines run 8 Pursuant to Chapter A-E 7 of the Wisconsin Administrative Code, marked 200'± back from R/W Parcel B Eagle Landmark Surveying, Inc. is required to meet certain Minimum Standards for Property Surveys as specified in Sections 7.01 through 7.07 of this code. Our client has agreed to exclude certain surveying S 86°44'59"W 1197.95 work from these requirements as allowed in Chapter A-E 7.01 (2). The requirements of Chapter A-E 7 of the Wisconsin Administrative Code's Minimum Standards for Property Surveys which have been waived are listed below: □ Field measurements and angles as described in (A-E 7.06). [X] Legal description prepared for this property (A-E 7.04). [X] Monuments marking all property corners (A-E 7.03 & 7.07). [X] Tie to a Public Land Survey System Corner (A-E 7.04). P.K. NAIL AS SHOWN ON GENISOT MAP I hereby certify, that to the best of my knowledge and belief, I have complied with the remaining requirements of Chapter A-E 7 of the I" IRON PIPE AS SHOWN ON GENISOT MAP #9134 Wisconsin Administrative Code, Minimum Standards for Property Surveys. DATED THIS 5TH DAY OF NOVEMBER, 1998 S-1410 COMPUTED POSITION JAMES L. WILL, RLS #1410 SURVEY FOR Eagle Landmark Surveying, Inc. 5035 Highway 70 West ART SENICKA EAGLE RIVER, WI. 54521 JOB #E1444