
OCS Area #. 1/16 Corner N89°42'00"E 968.20' 900 34' N88°55'52"E Squaw Lake Bearings Solar <u>\$89°09'00"W</u> 793 30' G L 2 SEC 8 G L 1 SEC 17 1/16 Corner Meander Corner 8"Maple, \$13°W, 29 2' 1-1/2" Iron pipe found Part of GOV'T. LOT 2

SECTION 8, T39N, R4E

Minocqua Township Oneida County, Wisconsin



I haraby cartify that I have surveyed the above described property and that the above map is a true representation thereof and shows the size and location of the property, its exterior boundaries, and the location of all visible structures and dimensions of all principal buildings thereon boundary fences, apparent sasements, roadways and visible encroachments

This survey is made for the use of the present owners of the property and also those who purchase, mortgage, or guarantee the little thereto within ons (1) year from the date hereof

I hereby certify that said survey and the above map were made in accordance with acceptable professional standards and that the information contained thereon is, to the best of my knowledge, information and belief, a true and accurate representation thereof

Any legal descriptions conforming to this survey have been provided

The above survey was made by order of Keith Jaeschke

• 2 1" Iron pipe found

• : 1-1/2" Iron pipe found

O = 1" Iron pipe set

Inman • Foltz and Associates, Inc surveyors

8612 highway 51 north minocqua wisconsin 54548 [715] 356-9485

RECEIVED & FILED #13....2... Oneida County Surveyor's Office