

SQUIRREL

LAKE

MAP # B3779
DATE FILED JAN 02 1980
BY
DESCRIPTION FILED
ONEIDA CO. SURVEYOR'S OFFICE

Erroneous iron pipe
S70°07'W, 44'

November 19, 1997

Recovered, verified, and marked monuments at the corners of 6B as follows:

- ▲ = 1" iron monument found in place and marked with lath stake.
- = 1 1/4" iron monument found in place and marked with lath stake.
- = 2 1/2" iron monument found in place and marked with lath stake.

This survey was completed by Foltz & Associates, Inc. for the purpose of locating existing lot corners by the order of Karl Altenburg, who has executed a written waiver for all other requirements of Wis. Adm. Code Chap. A-E 7.

Bearings Magnetic



- = Iron pipe found in place
- = Iron rod found in place
- = Iron pipe set
- ⊗ = Iron rod set

Part of
-MC KENNAS SUBDIVISION-

SECTION 20
T 39 N, R 5 E

Oneida County, Wis

Scale 1"=100'

May, 1971

Northwoods Surveyors Inc

William J. Cameron
Land Surveyor

SW - NE

NE - SW
ERSEMENT RD
NW - SE

LAKE
ROAD

SQUIRREL
ROAD

One-Quarter Line

J. Rein