

Note Description is provided on a separate sheet.

I have surveyed the above described property and the above map is a true representation thereof and shows the size and location of the property, its exterior boundaries, and location and dimensions of all visible structures thereon, fences, apparent easements and roadways and visible encroachments, if any.

This survey is made for the exclusive use of the present owners of the property, and also those who purchase, mortgage, or guarantee the title thereof within 1 (one) year from the date hereof; and as to them I warrant the accuracy of said survey and map.

Bearings are based on the North-South 1/4 line which bears S3°15'00" W as being of record.

Being a part of the
Northwest 1/4 of the Northeast 1/4
Section 7, T 38 N, R 11 E
Town of Three Lakes, Oneida Co., WI.

- 1-1/2 dia iron pipe found in place
- 1-1/4 dia iron pipe found in place
- 1 dia iron pipe found in place
- Mag nail set in pavement
- △ Computed angle point
- / Bearing & Distance of record

FENCE


Surveyor's Certificate

I hereby certify that I have surveyed and mapped the lands shown hereon and that, to the best of my knowledge and belief, said survey and map is a true and correct representation thereof and that I have complied with the Wisconsin Administrative Code A-E 7

Dated this 25th day of November 1996

Kip W. Soder

KIP W. SODER R.L.S. #1731
Soder Surveying
Three Lakes, WI. 54562



Survey For:
James Bollman

6980 Stanzil Street
Three Lakes WI. 54562

Scale 1" = 20' Date 11-25-98 Drwn By KWS

Soder Surveying
Three Lakes, WI.

Dwg No.
520

MAP #	B4084
DATE FILED	JAN 13 1999
BY	DAP
DESCRIPTION FILED	
ONEIDA CO. SURVEYOR'S OFFICE	