ONEIDA CO. SURVEYOR'S OFFICE

Lot 2 of CSM # 1799 and
Lot 8 of CSM # 1686
Part of the
SW 1/4 of the NE 1/4
SECTION 1, T 36 N, R 8 E
City of Rhinelander
Oneida County, Wisconsin

200 26' (200 34 Parking Area Encroachment 11JP Mowed Area Proposed Dividing Line WEST - LOT 2 -(N 2.46'26" BENCH MARKS 1 - 97 56' - Top of Fire Hydrant 2 - 98 33' - PK nail in curb 3 - 101 26' - Nail in light pole 4 - 102 21' - Top of iron pipe in concrete Scale 1" = 3015' S 87°13'23'W LEGEND 8 87 20'45"W 14NP 2 149 99 0 - 1" Iron Pipe Found MCMULLEN ▲ - Fire Hydrant ROAD 🗓 — Telephone Pedestal ■ - 3' X 3' Electric Box 目 − Manhole ⊗ - Water Valve ()— Recorded as values w_ — Mowed Area Registered Land Surveyor # 5+2555 (1) - Bench Mark Date 6/11/01 - LOT 8 6 10' MCMULLEN & ASSOCIATES, INC TREE KEY (ie. 18NP = 18" Norway Pine) Drafted By: Benton A McMyllen NP = Norway Pine
JP = Jack Pine
WP = White Pine SP = SpruceMowed Area S 8743'06" W (\$ 8745'03 **...149** 88' SURVEYOR'S CERTIFICATE I, Benton A McMullen, Wisconsin Registered Land Surveyor # S-2555, do hereby certify that I have surveyed and mapped the property shown hereon, and that I have complied with the applicable requirements of the Wisconsin Administrative Code Section A-E 7, and that this map represents a true and accurate survey of said property to the best of my knowledge and belief

1

 \Diamond

- - 2" Iron Pipe Found in Concrete

Area with an electric box and 2 telephone pedestals

Area with an electric box, 2 telephone pedestals, and 2 water valves

で る る

This survey was preformed under the order of Mary M Vinopal (Impact Seven, INC)

This survey is made for the use of the present owners of the property, and also those who purchase, mortgage, or guarantee the title thereto within one year from date hereof.