MAP # B4906 DATE FILED DEC 1 1 2001..... BY DESCRIPTION FILED ONEIDA CO. SURVEYOR'S OFFICE

Part of the NW 1/4 of the SE 1/4 **SECTION 7, T 38 N, R 7 E** Town of Lake Tomahawk Oneida County, Wisconsin

NOTE Flagged parcel lines with surveyor's tape are only a representation of the property line and should not be used as the actual property line

NOTE This survey was performed to stack out a proposed building site of 30' by 40' with no

NOTE setback distances used are as follows Sideyard Setback - 10 feet Road Setback - 20 feet from right-of-way EXTERIOR DESCRIPTION


Part of the NW 1/4 of the SE 1/4, Section 7, Township 38 North, Range 7 East, Town of Lake Tomahawk, Oneida County, Wisconsin more particularly

Commencing at the south 1/4 corner marked by a found W C.D brass capped iron pipe, thence N 0° 31' 41" E (Assumed), a distance of 1371.23 feet to a found which marks the easterly right-of-way line of Bird Lake Road, said point being the POINT OF BEGINNING;

Thence along said right-of-way northerly along the arc of a 52° 01' 48" degree curve 605 70 feet the center of which lies easterly with a radius of 667.00 feet and a long chord which bears N 2° 57' 16" W, a distance of 345 66 feet to a set 1 1/2" iron pipe; thence continuing along said right-of-way N 23° 03' 37" E, a distance of 92.82 feet to a found 1" iron pipe, thence leaving said right-of-way S 0° 31' 49" W, a distance of 669 75 feet to the POINT OF BEGINNING

Said described tract containing 0 88 acres (38549 81 square feet), more or less.

Subject to any easements, restrictions, or rights of way of record or of use, and to a perpetual easement for public utilities



Registered Land Surveyor # S-2555


MCMULLEN & ASSOCIATES, INC. Drafted By BENTON MCMULLEN

SURVEYOR'S CERTIFICATE

I, Benton A McMullen, Wisconsin Registered Land Surveyor # S-2555, do hereby certify that I have surveyed and mapped the property shown hereon, and that I have complied with the provisions of Chapter 236 34 of the Wisconsin Statues, and that property and the exterior boundaries to the best of my knowledge and belief

This survey was preformed under the order of Chris Warren

This survey is made for the use of the present owners of the property, and also those who purchase, mortgage, or guarantee the title thereto within one year from date hereof



LEGEND

O - 3/4" Iron Rod Found


• - 1" Iron Rod Found ○ -1" Iron Pipe Found
● -1 1/2" Iron Pipe Found

() - Recorded as values ▲ - Bore Hole

⊗ - Bench Mark (16" Twin Oak) (NOTE. Iron pipe diameter is outside diameter)

CURVE DATA Arc 605 70 Chord 585 10 Chord Bearing N 2°57'16"W Tangent 325 53

Radius 667 00



321 19

ROAD