

Chord 142.30 Chord Bearing S41*47'28" Delta Angle 36*10'23'' Radius Tangent 74.85 Service US HIGHWAY Arc 144.69 229.18 50' **FRONT** STREET N 86:10'32''W 75.92' 50.65' N 86°10'32"W 177.19 S 86°15'04"E 119.33' =2= =1= 94 =3= 123.50 49.95 74.59 50.22' 84 73.20 249.96 S 84°54'11"W Fence 2 and 3 are Scale=1'=50' together S 4°55'19"E 10%. 100' 0 50' 200 =Iron pipe found. O=Iron pipe set. or S1340 Date 5/16/97 SURVEYOR'S CERTIFICATE

I, David F McMullen, Registered Land Surveyor No. S-1340 hereby certify that we have surveyed the property described above; that this plat is an accurate survey and a true representation thereof and correctly show the exterior boundary lines and the correct measurements thereof; that we have made such survey by order of Bill River's, and that we have complied with Chapter 236.24 of Wisconsin State Statutes.

I hereby certify that I have surveyed the above described property and that the above map is a true representation thereof and shows the size and location of the property, its exterior boundaries, the location of all visible structures and dimensions of all principal buildings thereon, boundary fences, apparent easements, roadways and visible encroachment, if any.

This survey is made for the use of the present owners of the property, and also those who purchase, mortgage, or guarantee the title thereto within one year from date hereof.

<u>۳</u>