

L1717

L1717

ADDENDUM

to existing information for the

East quarter corner of Section 9, T. 35 N., R. 11 E.
Oneida County, Wisconsin.

A Certified Land Corner Restoration form was prepared by Philip T. Hanson, RLS-498, on April 15, 1975 and was filed in the Oneida County Register of Deeds office on October 1st, 1975.


On 10/27/96, I visited the corner and found it to be as described on the above mentioned Corner Restoration form. For maintenance to the corner I:

- Set a white vinyl sign post, 1' SSE of the corner monument;
- Set a 1" x 30" iron pipe on the section line running south and on the South right-of-way line of Stockley-Meister Road. Said pipe was set 46.85 feet from the corner monument. (see map of survey for John Sager);
- Set a 1 1/2" x 30" iron pipe 30.00 feet north of the corner monument. This pipe, the corner monument and the above mentioned 1" pipe form three points on a straight line;
- Set an aluminum nail in a low blaze on the right side of Hansons' red pine, NW, 16.42 feet, and I
- Set an aluminum nail in a low blaze on the right side of Hansons' white pine, NE, 10.63 feet.

I certify that this information is correct to the best of my knowledge and belief.

January 14, 1997

David E. Tlusty
David E. Tlusty, RLS-1390



MAP #	L 1717
DATE FILED	MAY 12 1997
BY
DESCRIPTION FILED
ONEIDA CO. SURVEYOR'S OFFICE	

L1717