## **SURVEY LANDMARK PRESERVATION RECORD**

It is the primary purpose of this record to preserve the location of any survey landmark subject to disturbance, removal or to be rendered inaccessible, as provided by Section 59.74(2), Perpetuation of Landmarks, Wisconsin Revised Statutes.

County:

City, Village, Town:

Section:

Town:

Range:

Oneida

Woodboro

24

36

7

Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 corner or other subdivisional corner; a monument called for in a deed; a monument shown on a survey map or plat ect. and in what Gov't Lot, 1/4-1/4 Section or other PLSS subdivisional tract.


May 7, 2008 - Prior to road construction we searched for the Northwest corner of the Southeast 1/4 of the Southwest 1/4 and found a P.K. Nall set by William Bandow per Plat of Survey dated 8/15/2002 — Oneida County Land Information Office Map Number B-5065. We also found a Railroad Spike set by Todd Loftus, North 56'30'42" East, 0.13' from the found P.K. Nail — See Certified Survey Map Number 2981.

November 7, 2008 - After road construction was complete we visited corner, checked the ties and set a Berntsen survey nail with cross on top to replace the previously found P.K. nail and set a railroad spike to replace the previously found railroad spike.

3607241030

Show approximate location of survey landmark on this Section diagram:

NW Cor. SE-SW



Plan view map of survey landmark location with bearing and distance ties to a minimum of four(4) described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material and/or described GPS method and precision.

14" Red Oak Tree blazed and a 60 P nail set in side ? of tree

Scale: \_\_1" = 30'

ACLENO


## Note

The corner lies approximately 6.5' North of the centerline of Squash Lake Road.

## Legend

- Found 3/4" Iron Rebar
- Set Berntsen Survey Nail with Cross on Top Δ
- **()** Found 1" Iron Pipe
- Set Railroad Spike





P.O.S. B5065



Also a railroad

spike was found

0.13

Seal



## PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This survey landmark is being referenced for the express purpose of location preservation and is not intended as an attestment of the legal significance and/or positional accuracy thereof.

Therefore, this survey landmark location should be further evaluated and verified for any future land surveying or related usage purposes

Jonathan W. Dulin, hereby certify that I am duly licensed as a Professional Land Surveyor in the State of Wisconsin; that the location of this survey landmark was referenced by me under my direct supervision and/or control; and that the information shown is true and correct to the best of my knowledge and belief.

Signed:

Date: ଠଃ

70