## LAND CORNER PRESERVATION RECORD It is the purpose of this record to preserve the location of a survey or land corner monument that may be disturbed, removed or inaccessible due to road construction or other activity. Section: City, Village, Town: Range: Oneida Little Rice T. 37 N. R. 5 E. Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 Approximate location within corner or other subdivisional corner; a monument called for in a deed; a monument shown on a Section 35, T37N, R5E survey map or plat etc and in what GL or ¼ - ¼ section or subdivision the monument is located. July 25, 2014: I searched for and did not recover the railroad spike described on survey map no. B-3028. I found and marked the Consolidated Papers 1" diam. iron pipe witness monument that bears East, 25 ft.

Plan view map of landmark monument location with bearing and distance ties to a minimum of four described witness or reference monuments of concrete, natural stone, metal, live bearing trees or equivalent material or indicate datum & coordinates if tied out using GPS. Indicate what was reset.

**NORTH** 

MAP # 23022
DATE FILED $9-14-15$
BY 212
DESCRIPTION FILED
ONEIDA CO. SURVEYOR'S OFFICE

## Seal:



## PROFESSIONAL LAND SURVEYOR CERTIFICATE:

This land corner was referenced out in advance of road construction or other activity as an act of preserving survey evidence or monuments. This corner has not been tested for its accuracy during the course of this preservation. It is recommended that those using the corner position evaluate and verify it prior to use in a survey or other use.

I hereby certify that I am a duly licensed Professional Land Surveyor in the State of Wisconsin; that the location of this Survey or Land Corner was referenced by me, for under my direct supervision and control and that the information shows on this record is true and correct to the best of my knowledge and beliefs

Signature

**8.3022** 

3705351000 PPECONSTRUCTION NOTHING FOUND