U.S. PUBLIC LAND SURVEY MONUMENT RECORD

NOTE: This form is intended and designed to fulfill all requirements of Wisconsin Administrative Code, Chapter A-E 7.08 U.S. Public Land Survey Monument Record. An additional sheet may be added if necessary to conform with said requirements.

CORNER LOCATION

Quarter Corner common to Sections 15 and 16 Township 35 North, Range 10 East of the 4th P.M. Town of Shoepke, Oneida County, Wisconsin

HISTORY OF ORIGINAL CORNER ESTABLISHMENT

ORIGINAL SURVEYOR:

James Nowlin

DATE OF SURVEY:

1865

DVIFO	JUN VLI.
ORIGINA	L ACCESSORIES:

6	5	4	3	2	1
7	8	9	10	11	12
18	17	16@	15	14	13
19	20	21	22	23	24
30	29	28	27	26	25
31	32	33	34	35	36

T35N - R10E

DESCRIPTION OF MONUMENT FOUND AT THIS CORNER AND IF IT WAS ACCEPTED, STATE ALL EVIDENCE (MATERIAL, TESTIMONIAL, OCCUPATIONAL, PLATS, RECORDS, OTHER MONUMENTS) USED AS A BASIS FOR ACCEPTING. IF NOT ACCEPTED OR IF NOTHING WAS FOUND, STATE EVIDENCE USED AS BASIS FOR ESTABLISHING LOCATION. IF RE-ESTABLISHED THROUGH LOST CORNER PROPORTIONATE METHODS, INDICATE ALL MONUMENTS, DISTANCES AND DIRECTIONS USED TO ESTABLISH. INDICATE TYPE OF MONUMENT AND SIGN POST FOUND OR SET.

6-1966 Kirby found corner by Hall near c/l (Genisot map #3730)

6-1980 Immich found corner

1990 William Kelly found iron under surface of road. Set R.R. Spike over iron. Set 3" aluminum witness monument and white post east of corner. Location of corner confirmed by local resident C.D. Schmeichel.

10-2004 Russell Brown found corner to be gone due to road construction. Set mag, nail per ties from Kelly's corner restoration sheet. Checked location with GPS using Trimble 5700/5800 and Harn base station 239s with coord's given by Oneida County Land Information Office. Corner position per ties and GPS location match.

6/14/2016 I visited corner location and found mag nail in northbound lane of CTH Q. I also found three remaining ties. Tie to tree as shown on 2004 tiesheet was overgrown. I also found an iron pipe to the east from a previous survey map #A1490. Set Iwo additional ties to the NE and SW to aid in resetting corner after upcoming road construction. Checked ties and accepted mag nail as being in the corner location. GPS'ed corner location in Oneida Co. Coordinates based in NAD 83-2011 with the corner location at N: 121,449.36 E: 308,911.97

PLAN VIEW OF CORNER WITH TIES TO AT LEAST 4 WITNESS MONUMENTS. IF IN DISAGREEMENT WITH PREVIOUSLY ESTABLISHED CORNER, SHOW THE DISTANCES BETWEEN THE TWO CORNERS AND ALSO INDICATE THE TIES TO THE DISPUTED.

