	LAND	CORNER PR	ESERVATIO	N RECORD	
It is the purpose of disturbed, removed	this record to prese d or inaccessible due	rve the location to road constri	of a survey or uction or other	land corner mo	nument that may be
County:	City, Village, Town		Section:	Town:	Range:
Oneida	Sugar Camp		17	38 North	10 East
Describe what was found, its location and origin. If known, describe if the monument found is a 1/16 corner or other subdivisional corner; a monument called for in a deed; a monument shown on a survey map or plat etc and in what GL or ¼ - ¼ section or subdivision the monument is located.				Approximate location within Section _17	
6/2/2017 I made a thorough s	earch of the area for a	any monumentati	on.		
I found nothing.					
					3810171000
GPS. Indicate what wa	ə, naturai stone, metal, li as reset.	ve bearing trees or	equivalent mater	ial or indicate datur	m & coordinates if tied out using NORTH ↑
				MAP 4	L3179
				Pâtr	L3179
				no.	3C
				toe.a.z	istyrae (* 1948)
				OKOTU	a Su. Surveyoris office
JEFFREY DEMUT S-2050 RHINELANI WI	PR Thi act not rec use H DER, Sta refi info kno	is land corner wa- ivity as an act of been tested for i ommended that t in a survey or of ereby certify tha ite of Wisconsin erenced by me	s referenced ou preserving surv ts accuracy dur those using the ther use. I am a duly lid that the locat munder my dir on this record	ey evidence or m ing the course of corner position ev censed Professi- ion of this Surve	cate: bad construction or other conuments. This corner has this preservation. It is byaluate and verify it prior to conal Land Surveyor in the eay or Land Corner was and control and that the frect to the best of my Call College Date