RECEIVED & FILED #1.42.4 Oneida' County Surveyor's Office State of Wisconsin / Department of Transportation County ONEIDA Zone Elevation (Z) N. Elevation (Z) Zone MEAN SEA LEVEL, 1929 ADJUSTMENT Order 13/40 in Genisot Surveyors dated 4.26-48 no longer exist. WILLIAM H. SCHERER
S-866
ST. GERMAIN,
WIS.
SURVEY

SURVEY


STALL SECTION SEAL Survey Supervisor

## RECORD AND CERTIFICATION OF U.S. PUBLIC LAND SURVEY CONTROL STATION

E-D-716-72

2000/6 Project 1. D. 1593-District EUGENE DAHL Range (E,W) Corner Township 8 E SECTION (x) Wisconsin Coordinates 2 168 CORNER Control Station Name East (X) North (Y) DATUM CONTROL NORTH AMERICAN, 1927 Vertical -Horizontal -CONTROL SURVEY ond Horizontal Order Vertical

## SKETCH



I hereby certify that on the  $9^{\frac{1}{2}}$  day of \_ 1974, that I did locate the above corner which was evidenced above ground ; I further certify that to perpetuate the location of such corner I did, at the exact location thereof, place a permanent marker consisting of I further certify that I did

located as shown above:

This work done by Eugene Duhl under the

Signature Registered Land, Surveyor

Registration No. S-- 866