RECEIVED & FILED # L.4.2.5
Oneida County Surveyor's Office
State of Wisconsin / Department of Transportation
Date.... JUN 2 8 1989
By.... JBM
DOS Area # Harlow Chief
DIVISION OF HIGHWAYS

RECORD AND CERTIFICATION OF U.S. PUBLIC LAND SURVEY CONTROL STATION

E-D-716-72

District	Project I. D.	Located by	
7	1593-0-00	Recovered EUGENE DAHL	

Corner	Township	Range (E,W)	County
N. 1/16 on W. line SECTION 12	36 N	8E	ONEIDA

Wisconsin Coordinates	East (X)	North (Y)	Elevation (Z)	Zone
CORNER	2,141,193.138	167,361.316		N.
Control Station Name	East (X)	North (Y)	Elevation (Z)	Zone

CONTROL DATUM
Horizontal — NORTH AMERICAN, 1927
Vertical — MEAN SEA LEVEL, 1929 ADJUSTMENT

SURVEY CONTROL
Horizontal — 2ND Order
Vertical — _____ Order

SKETCH



LOCATION SKETCH
(Location of landmark indicated by "X")



I hereby certify that on the 8th day of April 1974, that I did locate the above corner which was evidenced by a 1" Iron Pipe 0.3' below road surface; I further certify that to perpetuate the location of such corner I did, at the exact location thereof, ~~place a permanent marker consisting of~~ leave the 1" Iron Pipe intact; I further certify that I did establish 3 references ~~or witness monuments~~ consisting of a Power Pole, a 10" Triple Maple and the south rail of the Soo R.R. located as shown above:

Note: This work done by Eugene Dahl under the supervision of:

WISCONSIN
WILLIAM H. SCHERER
S-866
ST. GERMAIN, WIS.
LAND SURVEYOR

SEAL

Signature Registered Land Surveyor	Registration No.	Title
William H. Scherer	S-- 866	Survey Supervisor

CORNER N. 1/16 on W. line
SECTION 12
TOWN 36N
RANGE 8E