


SEC. 23 T. 39 N. R. 9 E.

① N¹/₄ NE¹/₄ at 20.114 (Mans 5/44) L627



② N¹/₄ Sec. 23 at 40.228 each way (Mans 5/46)

③ N¹/₄ NW¹/₄ at 20.114 (Mans 5/46)

RECEIVED & FILED **6 27 88**
 Ocala County Surveyor's Office
 Date: 1/5/88
 By: A.R.
 OCS Area #

4) NW Cor. Sec 23 (Gross copy I.P. ~~IP~~) at orig section corner

(Maine 5/46)


5) W¹/₄ NW¹/₄

6) W¹/₄ Sec 23 at 82.83 east of W¹/₄ Sec 22 on bearing of 11°08' feel
32 lks north of ¹/₄ post, OK but no bearings. (Vaughn 6/14/02) Cor is 81.80
west of E¹/₄ Cor. Sec 23 (~~Vaughn 6/11/1900~~) set post. PW 16" (dead) S60°E-26
lk (this B.T. might be for E¹/₄ Sec 23) (Vaughn 6/11/1900)

7) W¹/₄ SW¹/₄

SEC. 23 T. 39 N. R. 9 E. W.

① N¹/₄ NE¹/₄ at 20.114 (Manns 5/46) L 627



② N¹/₄ Sec 23 at 40.228 each way (Manns 5/46)

found tall 2" ip. w/w co b-c. (30' west of Lone Pine Rd.) No BT^s
made new BT^s Bw 10" S62°W 34.32'; SW 17" N39°W 15.83'
Asp 4" S65°E 2.32' (Seymour 11/28/88)

③ N¹/₄ NW¹/₄ at 20.114 (Manns 5/46)

④ NW Cor. Sec 23 Brass cap I.P. ~~(S)~~ at orig section corner

(Maine's 5/46) Found 1" I.P. ^{and} MS 6" S36°W 10.23', BW 14" S83°W 31.00', PR 22"
N 42°E 28.15' Made New B.T. MS 6" N38°W 18.65' (Visser's 3/15/95)

⑤ W¹/₄ NW¹/₄

⑥ W¹/₄ Sec 23 at 82.83 east of W¹/₄ Sec 22 on bearing of 11°08' feed

32 lbs north of ¹/₄ post, OK but no bearings. (Vaughn 6/14/02) Cor is 81.80

west of E¹/₄ Cor. Sec 23 (~~Vaughn 6/11/1900~~) set post. PW 10" (dead) S60°E-26
lb (this B.T. might be for E¹/₄ Sec 23) (Vaughn 6/11/1900)

⑦ W¹/₄ SW¹/₄