

067.

2 39 8

① N 1/4 NE 1/4

V & I	667.
J C	S y
J/N	1 1
B	r
GCS A	+

④	③	②	①
⑤			
⑥			
⑦			

② N 1/4 Sec 22

③ N 1/4 NW 1/4

1/4 NW Cor Sec 22 2' iron pipe P.J. 13 - N84 W-0782 ch,
J 14 - S30 W - 2 021 ch (Kus Valley dump 1938)


1/4 W 1/4 NW 1/1

1/4 W 1/4 Sec 22 Cedar post in hay marsh (Kus Valley dump 1938)

1/4 W 1/4 SW 1/4

22 39 8

① N 1/4 NE 1/4



② N 1/4 Sec 22 , 4 N 9 1/4 3 RS S 1 2 137 (17 h 4)

③ N 1/4 NW 1/4

④ NW 1/4 Sec 22 2' iron pipe PJ 13 - N84 W - 0782 ch,
PJ 14 - S30 W - 2 021 ch (Kiss Valley Imp 1938)

⑤ W 1/4 NW 1/4

⑥ W 1/4 Sec 22 Cedar post in hay marsh (Kiss Valley Imp 1938)

⑦ W 1/4 SW 1/4