

① N¹/₄ NE¹/₄


RECEIVED & L696M...

Onida County Surveyor's Office

Date FEB. 5 1988

By *SW*

OCS Area #.....



② N¹/₄ Sec 15 Iron pipe 1 1/2 lbs south of corner which is on rock. Oak 8
 N26°W - 0.252 ch. (Gen. cont 7/31/51)

③ N¹/₄ NW¹/₄

7) NW Cor. Sec 15 at 400± paces north of a post marked MC. in edge of swamp on north shore of McLeod Lake found oak post (about 10-12 years old) w sign of oyl. maples. B.T. found Bare PW (stp.) 22" S 70°W - 0.132 ch
PW 26" - N 15°E - 0.220. (Hall 5/21/30) Pine (stp.) 20" S 73°W - 0.138 ch
2nd (stp.) 30" - N 4°E - 0.223 (Geneset 7/31/51)

5) W 1/4 NW 1/4 Pine 12" - S 89°W - 40 (Don 9/26/44)

6) Meander Cor. - West line - South of Long Lake Found O.B.T. PW 10" (stp.)
S 20°E - 3 ch, birches gone. Found now in water. New B.T. PW 14" - N 4°E
- 67 ch.; PN 5" - S 40°E - 32 ch. (Hall 5/21/30)

7) Meander Cor. - West line - North of Brown Lake Found stp. of O.B.T. PW 20"
S 85°E - 16 ch, oyl birch pres. by clumps of second growth birches.. New B.T.
PW 18" - N 8°E - 0.675 (Hall 5/21/30)